

Sanas Accreditation Lab No.: T0066

Page 1 of 45

TEST REPORT

IEC 60 335-2-60

Safety of household and similar electrical appliances

Part: 2 Particular requirements for whirlpool baths

Report reference No HOUS/X0571
Tested by (printed name and signature) IT Mabena (Technical Signature) Signatory)
Date of issue 2004-07-23

This report is based on a blank test report that was prepared by FIMKO using information obtained from the TRF originator (see below).

SABS IEC 60 335-1:91 + A1:94 + A2:99 and SABS IEC 60335-2-

Testing Laboratory Name SABS – Testing and Conformity Services
Address Private Bag X191, Pretoria, 0001
Testing location SABS-TL
Applicant's Name Global Investments
Address PO Box 13515, N1 City

Goodwood, 7463
Test specification

Test procedure CB
Procedure deviation N/A

Standard....

Procedure deviation N/A

Non-standard test method N/A

Test Report Form

 Test Report Form No.
 1335-2-60/98-10

 TRF originator
 NEMKO

 Master TRF
 Dated 00-03

Copyright reserved to the bodies participating in the IECEE Schemes (CB and CB-FCS) and/or the bodies participating in the C.I.G (CCA-ENEC).

 Test item description
 Ozone Spa Machine

 Trademark
 Aqua O3 Zone

 Model and/or type reference
 AA-002

 Rating(s)
 220-240V 50Hz 2,1A 400W

Test items particulars:

Additional information None

National requirements None

Other requirements None

1 Dr Lategan Road Groenkloof, Private Bag X191 Pretoria 0001, Tel: +27 (012) 428-7911, Fax: +27 (012) 344-1568.

This test was performed by Testing and Conformity Services (Pty) Ltd, an affiliate of the SABS.

This report relates only to the specific sample(s) tested as identified herein. It does not imply SABS approval of the quality and/or performance of the item(s) in question and the test results do not apply to any similar item that has not been tested. (Refer also to the complete conditions printed on the back of the official test reports.)

